

Order ID: #41

Mercedes-Benz CLA 2021

Reserved

Generated on **14/03/2026**

VIN W1K1183881N123456 | EU 4415 NDK | Fuel: **Diesel** | Transmission: **Automatic**

Inspector's Conclusion

Vehicle is in good overall condition. The engine runs smoothly and the test drive showed no issues. Cosmetic findings: a scratch on the rear-left fender and a shallow dent on the front-left door. The front-left and rear-right tires are approaching the replacement threshold, and the driver's seat needs professional cleaning. Recommended with reservations.

Exterior	Interior	Engine & Mechanical
2 Issues	1 Issue	Healthy

Tires	Test Drive	Documents
Good	Smooth	Verified

Key Facts

- Keys: **2 Keys**
- Mileage (km): Mileage matches 42,500
- Documents: Verified
- Service History: Full History
- Previous Accidents: No evidence found
- Run & Drive: Yes Engine starts, car drives

Inspection Details

- Date: **14 March 2026, 11:42**
- Inspector: **Test Inspector**
- Inspector ID: **#29**

This report reflects the visual condition of the vehicle at the specific time of inspection. It is based on a non-intrusive assessment and test drive without disassembly or lifting. This report does not replace a comprehensive mechanical diagnostic. QOVO is not liable for hidden defects or issues arising after the inspection date. To verify the authenticity of this report, visit qovo.app/verify.

EXTERIOR INSPECTION



Front




Left side



Right side



Rear



#	Part	Damage	Severity	Inspector Note
1	Front Left Door	Dent	Med	Shallow dent on the front-left door with paint scuffing along the crease line. No deeper structural damage detected. Paintless dent repair feasible; light touch-up over the scuff recommended.
2	Left Rear Fender	Scratch	Med	Scratch along the rear-left fender, roughly 12 cm long, paint layer compromised but no metal deformation. Polishing or local touch-up recommended.

Damage Evidence



Front Left Door
Dent



Left Rear Fender
Scratch



Left Rear Fender
Scratch

This report reflects the visual condition of the vehicle at the specific time of inspection. It is based on a non-intrusive assessment and test drive without disassembly or lifting. This report does not replace a comprehensive mechanical diagnostic. QOVO is not liable for hidden defects or issues arising after the inspection date. To verify the authenticity of this report, visit qovo.app/verify.

Clean Parts — Photo Evidence


Hood


Roof


Front Bumper


Rear Left Light


Rear Right Light


Front Right Door


Left Front Fender


Right Rear Fender


Right Front Fender


Front Left Headlight


Front Right Headlight

Rest of Exterior is Clean

All other body panels, glass, and lights are in good condition with no defects.

This report reflects the visual condition of the vehicle at the specific time of inspection. It is based on a non-intrusive assessment and test drive without disassembly or lifting. This report does not replace a comprehensive mechanical diagnostic. QOVO is not liable for hidden defects or issues arising after the inspection date. To verify the authenticity of this report, visit qovo.app/verify.

INTERIOR CONDITION

#	Part	Damage	Severity	Inspector Note
1	Driver Seat	Stain	Low	Light stains on the seat cushion and side bolster, traces of regular use visible. The seat is intact but needs to be cleaned — professional upholstery cleaning recommended.

Damage Evidence



Driver Seat
Stain

Clean Areas — Photo Evidence


A/C & Heater


Rear Seats


Trunk Area


Steering Wheel

Rest of Interior is Clean
All other seats, trim, carpets, and electronics were inspected and found to be free of significant wear or damage.


WHEELS & TIRES DETAILS

Brand: **Michelin** Size: **225/45 R17** Type: **Summer**

Front Right (FR)
Condition: 6 mm
Rim Status: Good

Front Left (FL)
Condition: 4 mm
Rim Status: Good

Inspector's notes
Tread approaching replacement threshold.



Rear Right (RR)
Condition: 4 mm
Rim Status: Good

Inspector's notes
Mild uneven wear pattern.

Rear Left (RL)
Condition: 6 mm
Rim Status: Good

Spare Tire & Tools: Full-Size Spare Verified

This report reflects the visual condition of the vehicle at the specific time of inspection. It is based on a non-intrusive assessment and test drive without disassembly or lifting. This report does not replace a comprehensive mechanical diagnostic. QOVO is not liable for hidden defects or issues arising after the inspection date. To verify the authenticity of this report, visit qovo.app/verify.

ENGINE & TECHNICAL CONDITION

Engine Oil:	Level OK	Engine Start:	Instant
Coolant level:	Normal	Engine Sound:	Normal
Belts & Hoses:	Good Condition	Exhaust Smoke:	Clear
Active Leaks:	None Detected		

Dashboard: Check Eng (OFF) | Airbag (OFF) | ABS (OFF)

No photo

TEST DRIVE RESULTS

Transmission:

Shifting: **Smooth**

Clutch: **Good**

Braking:

Performance: **Sharp/Good**

Noise: **Silent**

Handbrake: **Holds**

Steering:

Alignment: **Straight**

Vibration: **None**

Noise: **Silent**

Suspension:

Ride Quality: **Solid**

Noises: **Silent**

Inspector's notes

Engine starts and runs smoothly. No issues observed.

This report reflects the visual condition of the vehicle at the specific time of inspection. It is based on a non-intrusive assessment and test drive without disassembly or lifting. This report does not replace a comprehensive mechanical diagnostic. QOVO is not liable for hidden defects or issues arising after the inspection date. To verify the authenticity of this report, visit qovo.app/verify.

DOCUMENTS & KEYS

VIN VIN Status

Verified Matches Chassis





Registration / Title

Present & Verified



Service History Full History Selected

Keys 2 Sets Counted

View High-Res Photos & Rate Your Inspector

Scan the QR code or tap the button to download the Qovo app and access the full digital report.

Download Qovo App

This report reflects the visual condition of the vehicle at the specific time of inspection. It is based on a non-intrusive assessment and test drive without disassembly or lifting. This report does not replace a comprehensive mechanical diagnostic. QOVO is not liable for hidden defects or issues arising after the inspection date. To verify the authenticity of this report, visit qovo.app/verify.